

CITROEN GRAND C4 PICASSO E-HDi 115 AIRDREAM AUTO EXCLUSIVE 5149 HZZ (MOTORCADE STOCK NO MC1185)



160.671Kms



03/11/2014



115 BHP



DIESEL



AUTOMATIC



105 g/km



OPTIONS

Extras Accessories:
Mixed Leather Finn Bitono Black / Gray Ardoise
Black Onyx (Solid)
Pack Drive Assist
Black Paint
Panoramic Glass Roof

Total options price : 4045,00 €

EQUIPMENTS

Type of vehicle tourism
Bodywork 7 Seat MPV
Color Black onyx
No. of doors 5
Power 115 BHP
Cilindrada 1.560 cm 3
Fuel Diesel
Date of 1st Reg 11/03/2014
Kms 160,671
Reg Number 5149 HZZ
V.I.N Number VF73A9HC8EJ771295

ADDITIONAL DESCRIPTION

DIRECT FROM ALD AUTOMOTIVE TO

(Motorcade Stock No MC1185)

Contacte con nosotros

Motorcade Cars SL
POLIGINO INDUSTRIAL LOS PERALES CAMINO DE COIN 66, MIJAS COSTA, MIJAS 29649,
MALAGA
952 666 116 or 665 960 064
motorcadespain@gmail.com
www.motorcadespain.com

PRICE
€13.995,00

10/28/20 16	10/31/ 2016	RIERA DUVAL, SL	Cost Management Authorization Strap accessories Replace front brake discs Replace front brake discs Replace front brake pads Replace rear brake pads Revision 100000Kms. Replace pollen filter Replace seals / seals Lubrication system Replace oil filter Replace air filter Replace fuel filter Replace oil Check / Replenish levels Strap accessories Revision 100000Kms. Replace air filter Revision 100000Kms. Review 100000Kms. Review 100000Kms. Review 100000Kms. Replace fuel filter Revision 100000Kms. Replace fuel filter Revision 100000Kms. Replace front brake discs Repair in front brake system Repair in front brake system Replace front brake pads Steering system repairs Steering system repairs Steering system repairs Steering system repairs Replacing pollen filter Revision 100000Kms. Replace inner covers and accessories Revision 100000Kms. Review 100000Kms. Replace oil Replace oil filter Replace air filter Replace fuel filter Replace pollen filter Cost Management Authorization Residual rate	102,704	
08/11/20 16	08/11/ 2016	F.LUIS CORNEJO SANCHEZ- GARAGE TANO	Strikers	91,920	2
03/14/20 16	03/16/ 2016	RIERA DUVAL, SL	Cost Management Authorization Review 75000Kms. Replace seals / gaskets lubrication system Replace oil filter Replace oil Check / Fill levels Revision 75000Kms. Replace oil Replace oil filter Cost Management Authorization Waste rate	76,892	
01/18/20 16	01/18/ 2016	F.LUIS CORNEJO SANCHEZ- GARAGE TANO	Back	67,519	2
10/16/20 15	10/16/ 2015	RIERA DUVAL, SL	Review 50000Kms.	52,363	
08/04/20 15	08/04/ 2015	NTCOS.FER NANDO CORNEJO, SL	Strikers	41,275	2
04/30/20 15	04/30/ 2015	SANJOSE SIERO	Review 25000Kms. Annual review	25,500	

OPTIONS Total options price : 4045,00 €Extras Accessories:

Mixed Leather Finn Bitono Black / Gray Ardoise
 Black Onyx (Solid)
 Pack Drive Assist
 Black Paint
 Panoramic Glass Roof

Total options price : 4045,00 €

CITROEN C4 1.6 E-HDi AUTO GRAND PICASSO 115 BHP EXCLUSIVE 5149 HZZ 2014

Date Ent.Wor kshop	Date Sal. Works hop	Provider	Detail	Number of Kilometers	Tires Changed
02/06/2018	02/06/2018	TALLER NTCOS VIELLA, CB	Strikers	160,315	2
01/25/2018	01/25/2018	SANJOSE SIERO	Replace inner left dust cover Convergence / drop / forward feed Complete vehicle geometry Repairs mechanical steering drive	158,504	
11/10/2017	11/10/2017	F.LUIS CORNEJO SANCHEZ-GARAGE TANO	Strikers	156,591	2
10/13/2017	10/13/2017	RIERA DUVAL, SL	Cost Management Authorization Headlight Replace front brake discs Replace front brake discs Replace front brake pad Revision 150000Kms. Replace pollen filter Repair oil sump Replace oil filter Replace air filter Replace fuel filter Replace oil Check / Fill light levels Repairs on doors / windows Revision 150000Kms. Review 150000Kms. Replace air filter Revision 150000Kms. Review 150000Kms. Review 150000Kms. Replace fuel filter Revision 150000Kms. Replace fuel filter Revision 150000Kms. Replace front brake discs Steering system repairs Steering system repairs Front brake system repair Repair front brake system Replace pollen filter Revision 150000Kms. Replace lids and interior accessories Review 150000Kms. Review 150000Kms. Replace oil Replace oil filter Replace air filter Replace fuel filter Replace pollen filter Cost Management Authorization Residual rate	151,556	
07/05/2017	07/05/2017	SANJOSE SIERO	Replace lamps Repair in exterior lighting installation	134,826	
06/22/2017	06/22/2017	Euromaster-Integrated	Back	134,401	2
05/02/2017	05/02/2017	CABAL AUTOMOCION SL	Cost Management Authorization Replace front wiper blades Replace lamps in outdoor lighting Revision 125000Kms. Repair oil sump Replace oil filter Strap accessories Replace oil Check / Fill levels Replace lamps in outdoor lighting Headlight Replace wiper blades Revision 125000Kms. Review 125000Kms. Belt accessories Review 125000Kms. Review 125000Kms. Review 125000Kms. Review 125000Kms. Review 125000Kms. Replace oil Replace oil filter Strap accessories Cost Management Authorization Waste rate	127,267	
04/18/2017	04/18/2017	VULCANIZA DOS BALDAJOS, SL	Strikers	125,175	2
11/17/2016	11/17/2016	SANJOSE SIERO	Belt accessories Tensioners / Rollers belt accessories	105,279	